



Starch Packer Yard – Contractor Access

What is the problem?


- People are walking through the Starch packer yard without communication
- Trucks and forklift interaction in the starch packer yard is high, the risk of injury is unacceptable

What are the risks?

- Forklift loading of trucks, forklifts entering and exiting the building
- Truck movement in and out of the yard gates for containers and to be loaded

What is the solution to the problem?

- Shoalhaven Starches have a no pedestrian ruling for the area highlighted on the map below.
- Contracted workers must be made aware of this (via toolbox)
- Penalties will be enforced for anyone walking through the yard without authorisation from the Starch Packer supervisor for the day



What are the new requirements?

- Pedestrian (worker / contractor) access to SD5, Cationic Starch, RD9, GD8, Stillage Control room, SD5 Control room must be via designated walkways.
- For genuine access for work or vehicles, please contact the starch packer on 4423 8397 – or speak with the yardman in the area prior to access.

From the 1st May 2023, contractors who are caught walking through the packer yard will have their induction cancelled and their company to provide explanation. Vehicle access is restricted unless permission is obtained from the starch packer supervisor

Aaron Ticehurst | Capital Engineering Manager

Visit www.manildra.com.au/contractor For more information and other site instructions, maps, rulebook, aerial photos and permits

SITE INSTRUCTION

